


H2O STOP: how to stop water ingress - in ground recessed luminaires -



An inaccurate installation of the luminaire with ineffective connection (insulating tape, self-amalgamating tape or sheath inaccurately used) may lead to water passage along the cable and consequently water ingress in the fitting.



All ground recessed luminaires are equipped with a H2O STOP system or resin coated devices giving effective protection against water passage along connecting cables.